

**ORG 8560**



## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A33C1E00002**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A33C1E00002 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A35C1E00Q02.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

Authorized Signatory

Signature

2013-1-29

Date





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A35C1E00003**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A35C1E00003 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A37C1E00003.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China

陈晓峰


Authorized Signatory

陈晓峰

Signature

2013-1-29

Date





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A37C1E00004**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A37C1E00004 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A39C1E00004.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

Authorized Signatory

Signature

2013-1-29

Date





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

---

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A39C1E00005**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A39C1E00005 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A30C1E00005.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.


We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,


**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China

陈晓峰

\_\_\_\_\_  
Authorized Signatory

  
\_\_\_\_\_  
Signature

2013-1-29  
\_\_\_\_\_  
Date





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

---

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A30C1E00006**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A30C1E00006 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A32C1E00006.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.


We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,


**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China

陈晓峰

Authorized Signatory

  
Signature

2013-1-29  
Date





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

---

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A32C1E00007**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A32C1E00007 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A34C1E00007.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

\_\_\_\_\_  
Authorized Signatory

Signature

Date

2013-1-29





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

---

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A34C1E00008**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A34C1E00008 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A36C1E00008.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.


We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China

陈晓峰

\_\_\_\_\_  
Authorized Signatory

  
\_\_\_\_\_  
Signature

2013-1-29  
\_\_\_\_\_  
Date







## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A36C1E00009**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A36C1E00009 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A38C1E00009.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

Authorized Signatory

Signature

Date

2013-1-29





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A38C1E00010**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A38C1E00010 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A34C1E00010.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

Authorized Signatory

Signature

2013-1-29

Date





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A3XC1E00011**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A3XC1E00011 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A36C1E00011.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

Authorized Signatory

Signature

Date

2013-1-29





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A31C1E00012**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A31C1E00012 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A38C1E00012.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

Authorized Signatory

Signature

Date

2013-1-29





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

---

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A33C1E00013**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A33C1E00013 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A3XC1E00013.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.


We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,


**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China

陈晓峰

\_\_\_\_\_  
Authorized Signatory

  
\_\_\_\_\_  
Signature

2013-1-29  
\_\_\_\_\_  
Date





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A35C1E00014**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A35C1E00014 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A31C1E00014.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

Authorized Signatory

Signature

Date

2013-1-29





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A37C1E00015**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A37C1E00015 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A33C1E00015.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

Authorized Signatory

Signature

Date

2013-1-29





## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A39C1E00016**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A39C1E00016 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A35C1E00016.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China


陈晓峰

Authorized Signatory

Signature

Date

2013-1-29







## 柳州五菱专用汽车制造有限公司

Liuzhou Wuling Special-purpose Vehicle Manufacturing CO., Ltd.

---

2013 January 28

National Highway Traffic Safety Administration  
Office Vehicle Safety and Standards  
NEF-1, Room 5321  
400 7<sup>th</sup> Street SW  
Washington, DC 20590 USA

From: Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.

**Subject: Incorrectly computed VIN checksum digit for VIN LLWCL0A30C1E00017**

Dear Sir or Madam:

Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd. of China is the maker of a battery-electric low speed vehicle (LSV) imported into the United States by Alvarez Electric Motors Company of Riverside, California called the EcoCentre Eco-E™.

In the spring of 2012, several Eco-E vehicles were assigned, during manufacturing, VIN numbers with incorrect checksum digits in Position 9. These errors were not discovered until the vehicles were in the possession of the US dealer.

Pursuant to federal regulations, Wuling hereby notifies NHTSA/OVSS that Eco-E VIN LLWCL0A30C1E00017 has an incorrectly computed checksum number. The correct VIN number would have been LLWCL0A37C1E00017.

A copy of this letter will be provided to the purchaser of the vehicle. If for any reason a law enforcement officer or other official needs to further information, they should contact the Vice President of Operations, Alvarez Electric Motors Company, at 888.642.8806 or at [info@ecocentre.us](mailto:info@ecocentre.us). The mailing address is 6220 River Crest Drive, Riverside, California 92507.

We apologize for this inconvenience. The cause of this error has been corrected and future vehicles will be correctly assigned VIN numbers.

Sincerely,

**For:** Liuzhou Wuling Special-purpose Vehicle Manufacturing Co., Ltd.  
NO.17, Xihuan Road, Liuzhou City, Guangxi, Peoples' Republic of China

陈晓峰

\_\_\_\_\_  
Authorized Signatory

\_\_\_\_\_  
Signature

\_\_\_\_\_  
Date

2013-1-29

